Friday, 07/07/2006 8:59:14 AM

ĕser:

#### **Process Sheet**

Customer Job Number

Prsht Rev.

First Issue

Written By

**Previous Run** 

: CU-DAR001 Dart Helicopters Services

: 27584

**Estimate Number** 

: 11800 : NIA

P.O. Number This Issue

: 07/07/2006

:NIA

S.O. No. : NA

: NC

: 15/06/2006

: PURCHASED PARTS

Type

**Drawing Number Project Number** 

**Drawing Revision** 

**Drawing Name** 

**Part Number** 

Material **Due Date**  : SPACER KIT

: D25253

: D2525 REV B

: N/A

:NIA

: 30/06/2006

Qty: 20 Um: Each

Checked & Approved By

Comment

: Est. B99.11.10

Re-format added Acid etch stepEC

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

M6061T6R0750 1.0

Comment: Qty.:

0.0220 f(s)/Unit

Total: 0.4400 f(s)

6061-T6 Round Bar .750"

M1001

6061-T6 Round Bar .750"

LATHE CONV. 2.0



Comment: CONVENTIONAL LATHE

QC2

PARTS AS THEY COME OFF MACHINE

SECOND CHECK



20

4.0

3.0

QC8



Comment: SECOND CHECK

 $\sigma$ 

HAND FINISHING

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

6.0

Comment: INSPECT WORK TO CURRENT STEP

INSPECT WORK TO CURRENT STEP





06-07-13 6 Perm. Choruge. (Ed. 07.25)

٤.

Friday, 07/07/2006 8:59:14 AM Date: User: Linda Lacelle **Process Sheet** Drawing Name: SPACER KIT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27584 Part Number: D25253 Job Number: Seq. #: Description: **Machine Or Operation:** PACKAGING 1 PACKAGING RESOURCE #1 **Comment: PACKAGING RESOURCE #1** Identify and Stock Location: 8.0 Comment: DOCUMENT CONTROL Inspection Level 21 Le Re. 07-15 Job Completion

Üser:

Thursday, 6/15/2006 1:50:32 PM

Kim Johnston

#### **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**  : 27584

P.O. Number

: 11800

This Issue

Prsht Rev.

First Issue **Previous Run**  : 6/15/2006

: NC

: //

Type

S.O. No. :

: PURCHASED PARTS

**Drawing Number** 

**Drawing Name** 

Part Number

. D2525 REV B

**Project Number Drawing Revision** 

: N/A : B

: D25253

: SPACER KIT

Material **Due Date** 

: 6/30/2006

Qty:

20 Um:

See Replacent W/o astacled

Each

Written By

Checked & Approved By

Comment

: Est. B99.11.10

Re-format added Acid etch stepEC

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

**PURCHASING** 

1.0

PG

Comment: PURCHASING

Make as per Dwg D2525

Material release note required

Batch:

Total: 20.0000 Each(s)

Spacer Kit

PACKAGING RESOURCE #1

QC8

Comment: Qty .:



Comment: PACKAGING RESOURCE #1



Recieive & Inspect for Transit Damage

:0000 Each(s)/Unit

Ensure Material Release Note is attached

4.0

<del>-- QC</del>6

DIMENSIONAL CHECK

Comment: DIMENSIONAL CHECK

5.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
				5				
							<u> </u>	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC Corrective Action Section B				Verification Approval	Approval				
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC inspector			
						ļ					
				•							

Part No:	PAR #:	Fault Category:	NCR	Yes	No	DQA:	 Date:	
NOTE: Date & initial all entries				QA:	N/C C	losed:	Date:	•

Date: <sup>4</sup> Thursday, 6/15/2006 1:50:32 PM User: Kim Johnston **Process Sheet** Drawing Name: SPACER KIT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27584 Part Number: D25253 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: DOCUMENT CONTROL 8.0 DC Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion 

Form: rprocess

Page 2

### **Dart Aerospace Ltd**

W/O:		WORK ORDER CH	ANGES	<del></del>			
DATE	STEP PROCEDURE CHANGE	Ву	Date	Qty	<b>Approval</b> Mfg / Design Mgr	Approval QC Inspector	
	1				<u> </u>	<u> </u>	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	<u> </u>	Verification	Annuaral	Annroyal			
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector			
					-						
	<del> </del>										
	,										
•											


Part No:	PAR #:	Fault Category:	NCR:	Yes No	DQA:	Date:	
NOTE: Date & initial all entries				QA: N/C	losed:	Date:	*



DESIG	BW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	•
CHEC	KED,	APPROVED	DRAWING NO.	REV. B
	HE	# T	D2525 SHEET	1 OF 1
DATE			TITLE	SCALE
99.0	9.30		SPACER KIT	1:1
Α		95.12.22	NEW ISSUE	
В		99.09.30	REVISED MATERIAL	

RELEASED 199, 10. 12 KE

PART NUMBER	THICKNESS T	QTY
D2525-1	0.750	1
D2525-3	0.250	1
D2525-5	0.125	4
D2525-7	0.063	0
D2525-9	0.032	` 0



SHOP COPY

MATERIAL: 5052-H32 (QQ-A-225/7) OR 1100 (QQ-A-225TVRN TO OR 6061-T6 (QQ-A-225/8) OR 6061-T6 (QQ-A-200/8) TROLLED COPY

FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4 SUBJECT TO AMENDMENT WITHOUT NOTICE

DART AEROSPACE LTD	Work Order: 27584
Description: SPACER	Part Number: D25283
Inspection Dwg: \$255, Rev:	Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
,515	+.008 010 +.010	1517				
.750	+.010	,750 ,250				
,750 ,250	+.010	,250				
,	•					
	·					
	·					

Measured by:	Audited by: 5D	Prototype Approval:	-
Date: 06/67/11	Date: 66.67.11	Date:	

Rev	Date	Change	Revised by	Approved
A		New Issue	KJ/JLM	

